

## TRICON Version 10.2.2 Approved Components List - Certificate-No.: EZ 105.06/06




Revision list of hardware and firmware of the TRICON System v10.2.2

Module Name	Model	Firmware
ACM Advanced Comm. Module	4609	4930+5584
AI 0-10V DC (NIAI)	3701, 3701N2	5661
AI 0-5/0-10V DC (EIAI)	3703E, 3703EN	5916
AI 0-5V DC (NIAI)	3700, 3700A	5661
AI (DCCoupled Thermocouple) (NIAI)	3706A	5661
AI 0-5/0-10V DC coupled, commoned (HDI)	3704E	5910
AI Isolated Thermocouple (EIAI)	3708E, 3708EN	5916
AI Differential Analog Input, 32 points	3721, 3721N	6200 Build 92
AI Single-ended Analog Input, 64 points	3720	6200 Build 92
AO 4-20 (EAO)	3805E, 3805HN	5897
DI 115V AC/DC HiKV (EDI)	3501T, 3501TN2	5909
DI 24/48V DC (HDI)	3504E	5910
DI 24V AC/DC (EDI)	3503E, 3503EN2	5909
DI 24V DC Single (SDI)	3564	5504
DI 24V DC (Low Threshold) (EDI)	3505E	5909
DI 48V AC/DC (EDI)	3502E, 3502EN2	5909
DO 115V AC non Commoned (EDO)	3601T, 3601TN	5781
DO 120V DC Supervised (HiKV) (TSDO2)	3623T, 3623TN	5940
DO 120V DC (HVDO)	3603T, 3603TN	6142
DO 24V DC (Dual) (DDO)	3664	5492
DO 24V DC (FS) (DDO FS)	3674	5493
DO 24V DC non Commoned (EDO)	3604E	5781
DO 24V DC Supervised (TSDO2)	3624	5940
DO 48V DC non Commoned (EDO)	3607E, 3607EN	5781
DO 24V DC Supervised (ESDO)	3614E, 3615E	5784
DO 48V DC Supervised (ESDO)	3617E	5784
DO 24V DC Supervised, 32 points	3625,3625N	6213 Build 92
EICM Enhanced Intelligent Communication Module	4119, 4119A	4930+5276
MP EMP III	3008, 3008N	6198 (ET SX) 6054 (IOCCOM) Build 92
NCM Network Interface Module	4329	4930+5721
NCMG Network Interface Module	4329G	4930+5721
PI Pulse Input (EPI)	3510/3511, 3511N	5647
PT 24V DC (PT)	3515	5503
RO Dry Contact HighKV (ERO)	3636T, 3636TN	5777

TRICONEX	TUV Rheinland Industrie Service GmbH
Invensys Systems, Inc.	Automation, Software & Information Technologie
15345 Barranca Parkway	Am Grauen Stein
USA-Irvine, California 92618	51101 Köln
Revised Appendix A of Report-No.: 968/EZ 105.06/06	
Appendix G of Report-No.: 968/EZ 105.10/07	Page 1 of 2

2008-06-19

Module Name	Model	Firmware
RXM Primary Single Mode Fiber (SRXMP)	4210	3310
RXM Primary (RXMP)	4200, 4200N	3310
RXM Remote Single Mode Fiber (SRXMS)	4211	3310
RXM Remote (RXMS)	4201, 4201N	3310
SMM Safety Manager Module	4409	5660+4508
TCM Tricon Communication Module	4351A, 4352A, 4352AN	6136 Build 92
TS1131 Workbench, CEM Editor, Workbench Demo (TS1131 V3.X and V4.0: Windows NT 4, SP5 or later; Windows 2000, SP2 or later) TS 1131 V4.1: Windows 2000, SP2 or later, Windows XP Professional	-	V4.1.437
Enhanced Diagnostics Monitor (EnDM)	-	V1.1.111

	Manufacturer	Test Institute	Certifier
Signature	 N. Desai	 O. Busa	 H. Gall
Date	2008-06-19	2008-06-19	2008-06-19

**Document revision**

Date	Change	Author
2007-10-27	Initial revision	Bu/968
2008-06-19	Updated model numbers of Nuclear qualified modules as requested by Triconex	Bu/968

TRICONEX	TUV Rheinland Industrie Service GmbH
Invensys Systems, Inc.	Automation, Software & Information Technologie
15345 Barranca Parkway	Am Grauen Stein
USA-Irvine, California 92618	51101 Köln
Revised Appendix A of Report-No.: 968/EZ 105.06/06 Appendix G of Report-No.: 968/EZ 105.10/07	Page 2 of 2